



ECHOMASTER

Technical Bulletin

**West Coast
Operations**
2500 East Francis St.
Ontario, CA 91761
800-854-3133
727-573-9326 (Fax)

**Corporate
Headquarters**
15500 Lightwave Drive Suite 202
Clearwater, FL 33760
800-488-2267
727-573-9326 (Fax)

Models Affected : FC-GMHD101-MC
FCTP-GMHD05

Stated Complaint:

Confusion on compatible side mirror RPO codes for the Echomaster FC and FCTP, blindspot camera towing package for HD trucks.

COMPATIBLE



GM RPO CODE: DQS

- Integrated turn signals
- Heated
- Folding



GM RPO CODE: DPN

- Integrated turn signals
- Manual folding

NOT COMPATIBLE



GM PRO CODE: DF2

- No turn signals
- Manual folding



GM RPO CODE: DL3/DL8

- No Turn Signals
- Manual Folding